

## MATERIALE DE SUDARE – PARWELD

### ELECTROZI PENTRU SUDAREA OTELURILOR CARBON

Simbol Parweld	Simbol AWS	Simbol EN	kg /pac x nr.pac	L	Ø
<b>Electrozi OL TITANICI</b>					
6013	E 6013	E 42 A RC 11	5,0 x 4 = 20,0	300	2,0
			5,0 x 4 = 20,0	350	2,5
			5,0 x 4 = 20,0	350	3,2
			5,0 x 4 = 20,0	400	4,0
<b>Electrozi OL BAZICI</b>					
7018	E 7018	E 42 B 32 H 5	5,0 x 4 = 20,0	350	2,5
			5,0 x 4 = 20,0	350	3,2
			5,0 x 4 = 20,0	400	4,0

### SARMA PENTRU SUDAREA OTELURILOR CARBON

Simbol Parweld	Simbol AWS	Simbol EN	kg / rola	Ø
<b>Sarma OL sudare MAG</b>				
G3Si1	ER 70 S-6	G 42 3 M G3Si	5,0	0,6
			5,0	0,8

### SARMA cu AUTOPROTECTIE pentru SUDAREA OTELURILOR

Simbol Parweld	Simbol AWS	Simbol EN	kg / rola	Ø
<b>Sarma tubulara autoprotejata</b>				
MWFC09	E71-GS	-	0,45	0,9
MWFC509	E71-GS	-	5,0	0,9

### SARMA INOX

Simbol Parweld	AWS A5.9	EN 14343	kg / rola	Ø
<b>Sarma inox 316</b>				
ER 316 LSi	ER 316 LSi	G19 12 3 LSi	0,7	0,8

### SARMA PENTRU SUDAREA NEFEROASELOR

Simbol Parweld	Simbol AWS	Simbol EN	kg / rola	Ø
<b>Sarma OL sudare MAG</b>				
AlMg5 PW 5356	ER 5356	SG-AlMg 5	0,5	0,8
			0,5	1,0
			0,5	1,2